

FIG.1





FIG.2



## ASSIGNING PROCESS OF EXPOSURE GRADATIONS TO RESPECTIVE ELEMENTS

[illegible]

FIG.4

ASSIGNING PROCESS OF EXPOSURE GRADATIONS TO RESPECTIVE ELEMENTS

	0	1	2	3	4	5	6	7	...	...	...	255	256	257	...	...	510	511	...	...	...	765
R ELEMENT 1	0	1	2	3	4	5	6	7	...	...	...	255	255	255	...	...	255	255	...	...	...	255
R ELEMENT 2	0	0	0	0	0	0	0	0	...	...	...	0	1	2	...	...	255	255	...	...	...	255
R ELEMENT 3	0	0	0	0	0	0	0	0	...	...	...	0	0	0	...	...	0	1	...	...	...	255




FIG.6

	$n_i$	$m_i$	$n_i \times (m_i - 1) + 1$
R	4	256	1021
G	3	341	1021
B	2	511	1021

FIG.7

	$n_i$	$m_i$	$n_i \times (m_i - 1) + 1$
R	4	256	1021
G	3	512	1534
B	2	512	1023

FIG.8  
PRIOR ART




FIG.9






FIG.10




FIG.11




FIG.12

	$n_i$	$m_i$	$n_i \times (m_i - 1) + 1$
R	32	128	4065
G	16	256	4081
B	16	256	4081

FIG.13




FIG.14

